

Proposed Rules

Federal Register

Vol. 60, No. 173

Thursday, September 7, 1995

This section of the FEDERAL REGISTER contains notices to the public of the proposed issuance of rules and regulations. The purpose of these notices is to give interested persons an opportunity to participate in the rule making prior to the adoption of the final rules.

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. 94-NM-196-AD]

Airworthiness Directives; Airbus Model A310 and A300-600 Series Airplanes

AGENCY: Federal Aviation Administration, DOT.

ACTION: Notice of proposed rulemaking (NPRM).

SUMMARY: This document proposes the adoption of a new airworthiness directive (AD) that is applicable to certain Airbus Model A310 and A300-600 series airplanes. This proposal would require a functional flow test and leak test to verify if the pressure reducing valve in the cargo fire extinguishing system is in a serviceable condition, and replacement of any faulty valve with a new valve prior to extended range twin-engine operations of the airplane. This proposal is prompted by a report that, during a scheduled maintenance check, an inoperative pressure reducing valve was found in the cargo fire extinguishing system. The actions specified by the proposed AD are intended to ensure that a faulty pressure reducing valve is not installed, which could result in reduced fire protection of the cargo compartment of the airplane.

DATES: Comments must be received by October 17, 1995.

ADDRESSES: Submit comments in triplicate to the Federal Aviation Administration (FAA), Transport Airplane Directorate, ANM-103, Attention: Rules Docket No. 94-NM-196-AD, 1601 Lind Avenue, SW., Renton, Washington 98055-4056. Comments may be inspected at this location between 9:00 a.m. and 3:00 p.m., Monday through Friday, except Federal holidays.

The service information referenced in the proposed rule may be obtained from Airbus Industrie, 1 Rond Point Maurice

Bellonte, 31707 Blagnac Cedex, France. This information may be examined at the FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington.

FOR FURTHER INFORMATION CONTACT: Charles Huber, Aerospace Engineer, Standardization Branch, ANM-113, FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington 98055-4056; telephone (206) 227-2589; fax (206) 227-1149.

SUPPLEMENTARY INFORMATION:

Comments Invited

Interested persons are invited to participate in the making of the proposed rule by submitting such written data, views, or arguments as they may desire. Communications shall identify the Rules Docket number and be submitted in triplicate to the address specified above. All communications received on or before the closing date for comments, specified above, will be considered before taking action on the proposed rule. The proposals contained in this notice may be changed in light of the comments received.

Comments are specifically invited on the overall regulatory, economic, environmental, and energy aspects of the proposed rule. All comments submitted will be available, both before and after the closing date for comments, in the Rules Docket for examination by interested persons. A report summarizing each FAA-public contact concerned with the substance of this proposal will be filed in the Rules Docket.

Commenters wishing the FAA to acknowledge receipt of their comments submitted in response to this notice must submit a self-addressed, stamped postcard on which the following statement is made: "Comments to Docket Number 94-NM-196-AD." The postcard will be date stamped and returned to the commenter.

Availability of NPRMs

Any person may obtain a copy of this NPRM by submitting a request to the FAA, Transport Airplane Directorate, ANM-103, Attention: Rules Docket No. 94-NM-196-AD, 1601 Lind Avenue, SW., Renton, Washington 98055-4056.

Discussion

The Direction Générale de l'Aviation Civile (DGAC), which is the

airworthiness authority for France, recently notified the FAA that an unsafe condition may exist on certain Model A310 and A300-600 series airplanes. The DGAC advises that it received a report indicating that, during a scheduled maintenance check, an inoperative pressure reducing valve was found in the cargo fire extinguishing system. The valve had accumulated 10,587 total flight hours. The cargo fire extinguishing system is equipped with two fire extinguishing bottles. In a smoke warning incident, bottle number one is manually activated. After 60 minutes, bottle number two is discharged to maintain the required halon concentration for an additional 200 minutes for extended range twin-engine operations (ETOPS), yielding (giving) a total cargo fire protection time of 260 minutes. The discharge of bottle number two is regulated by the pressure reducing valve. A faulty pressure reducing valve, if not corrected, could result in reduced fire protection of the cargo compartment of the airplane from 260 minutes to 60 minutes.

Airbus has issued All Operators Telex AOT 26-13, dated June 28, 1994, which describes procedures for a functional flow test and leak test to verify if the pressure reducing valve in the cargo fire extinguishing system is in a serviceable condition. The DGAC classified this service bulletin as mandatory and issued French airworthiness directive 94-186-164(B), dated August 17, 1994, in order to assure the continued airworthiness of these airplanes in France. In addition, the French airworthiness directive specifies that ETOPS flights are not permitted if a faulty valve is found and not replaced.

This airplane model is manufactured in France and is type certificated for operation in the United States under the provisions of section 21.29 of the Federal Aviation Regulations (14 CFR 21.29) and the applicable bilateral airworthiness agreement. Pursuant to this bilateral airworthiness agreement, the DGAC has kept the FAA informed of the situation described above. The FAA has examined the findings of the DGAC, reviewed all available information, and determined that AD action is necessary for products of this type design that are certificated for operation in the United States.

Since an unsafe condition has been identified that is likely to exist or

develop on other airplanes of the same type design, the proposed AD would require a functional flow test and leak test to verify if the pressure reducing valve in the cargo fire extinguishing system is in a serviceable condition. The tests would be required to be accomplished in accordance with the all operators telex described previously.

The proposed AD would also require that, if a faulty pressure reducing valve is installed, it must be replaced with a new valve prior to further operation of the airplane under ETOPS. The replacement would be required to be accomplished in accordance with the aircraft maintenance manual.

As a result of recent communications with the Air Transport Association (ATA) of America, the FAA has learned that, in general, some operators may misunderstand the legal effect of AD's on airplanes that are identified in the applicability provision of the AD, but that have been altered or repaired in the area addressed by the AD. The FAA points out that all airplanes identified in the applicability provision of an AD are legally subject to the AD. If an airplane has been altered or repaired in the affected area in such a way as to affect compliance with the AD, the owner or operator is required to obtain FAA approval for an alternative method of compliance with the AD, in accordance with the paragraph of each AD that provides for such approvals. A note has been included in this notice to clarify this long-standing requirement.

The FAA estimates that 48 airplanes of U.S. registry would be affected by this proposed AD, that it would take approximately 1 work hour per airplane to accomplish the proposed actions, and that the average labor rate is \$60 per work hour. Based on these figures, the total cost impact of the proposed AD on U.S. operators is estimated to be \$2,880, or \$60 per airplane.

The total cost impact figure discussed above is based on assumptions that no operator has yet accomplished any of the proposed requirements of this AD action, and that no operator would accomplish those actions in the future if this AD were not adopted.

The regulations proposed herein would not have substantial direct effects on the States, on the relationship between the national government and the States, or on the distribution of power and responsibilities among the various levels of government. Therefore, in accordance with Executive Order 12612, it is determined that this proposal would not have sufficient federalism implications to warrant the preparation of a Federalism Assessment.

For the reasons discussed above, I certify that this proposed regulation (1) is not a "significant regulatory action" under Executive Order 12866; (2) is not a "significant rule" under the DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979); and (3) if promulgated, will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act. A copy of the draft regulatory evaluation prepared for this action is contained in the Rules Docket. A copy of it may be obtained by contacting the Rules Docket at the location provided under the caption **ADDRESSES**.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Safety.

The Proposed Amendment

Accordingly, pursuant to the authority delegated to me by the Administrator, the Federal Aviation Administration proposes to amend part 39 of the Federal Aviation Regulations (14 CFR part 39) as follows:

PART 39—AIRWORTHINESS DIRECTIVES

1. The authority citation for part 39 continues to read as follows:

Authority: 49 USC 106(g), 40101, 40113, 44701.

§ 39.13 [Amended]

2. Section 39.13 is amended by adding the following new airworthiness directive:

Airbus Industrie: Docket 94-NM-196-AD.

Applicability: Model A310 and A300-600 series airplanes on which Airbus Modification 6403 (reference Airbus Service Bulletin A310-26-2010 or A300-600-26-6011) has been installed; certificated in any category.

Note 1: This AD applies to each airplane identified in the preceding applicability provision, regardless of whether it otherwise has been modified, altered, or repaired in the area subject to the requirements of this AD. For airplanes that have been modified, altered, or repaired so that the performance of the requirements of this AD is affected, the owner/operator must use the authority provided in paragraph (b) of this AD to request approval from the FAA. This approval may address either no action, if the current configuration eliminates the unsafe condition; or different actions necessary to address the unsafe condition described in this AD. Such a request should include an assessment of the effect of the changed configuration on the unsafe condition addressed by this AD. In no case does the presence of any modification, alteration, or repair remove any airplane from the applicability of this AD.

Compliance: Required as indicated, unless accomplished previously.

To ensure that a faulty pressure reducing valve in the cargo fire extinguishing system is not installed, which could result in reduced fire protection of the cargo compartment of the airplane from 260 minutes to 60 minutes, accomplish the following:

(a) Prior to the accumulation of 600 total flight hours after the effective date of this AD, perform a functional flow test and leak test to verify if the pressure reducing valve in the cargo fire extinguishing system is in a serviceable condition, in accordance with paragraph 4.2., Description, of Airbus All Operators Telex AOT 26-13, dated June 28, 1994. If a faulty pressure reducing valve is installed, prior to extended range twin-engine operations (ETOPS), replace it with a new valve, in accordance with the aircraft maintenance manual, reference 26-23-14, Page block 401.

(b) An alternative method of compliance or adjustment of the compliance time that provides an acceptable level of safety may be used if approved by the Manager, Standardization Branch, ANM-113, FAA, Transport Airplane Directorate. Operators shall submit their requests through an appropriate FAA Principal Maintenance Inspector, who may add comments and then send it to the Manager, Standardization Branch, ANM-113.

Note 2: Information concerning the existence of approved alternative methods of compliance with this AD, if any, may be obtained from the Standardization Branch, ANM-113.

(c) Special flight permits may be issued in accordance with sections 21.197 and 21.199 of the Federal Aviation Regulations (14 CFR 21.197 and 21.199) to operate the airplane to a location where the requirements of this AD can be accomplished.

Issued in Renton, Washington, on August 31, 1995.

Darrell M. Pederson,

Acting Manager, Transport Airplane Directorate, Aircraft Certification Service.

[FR Doc. 95-22210 Filed 9-6-95; 8:45 am]

BILLING CODE 4910-13-U

14 CFR Part 39

[Docket No. 95-NM-53-AD]

Airworthiness Directives; Boeing Model 747-400 Series Airplanes

AGENCY: Federal Aviation Administration, DOT.

ACTION: Notice of proposed rulemaking (NPRM).

SUMMARY: This document proposes the superseding of an existing airworthiness directive (AD), applicable to certain Boeing Model 747-400 series airplanes,